

Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang

Email: engineer@iclab-cn.com



Project Inspection Report

Company : NA

Address : NA

Sample Name : ADXL357BEZ-RL7

Dis. Shenzhen China

Tel: 0755-83765367

Manufacture : ADI

Date Code : 2108,2106,2113

Package Type : <u>CLCC14</u>

Sample Number : 2500 PCS

Check Number : 122 PCS

Date of Received : 08/30/2021

Date of Tested : 10:30/08/31/2021 ~ 17:10/09/02/2021

WE HEREBY CERTIFY THAT:

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

Inspected by Engineer	Reviewed by Project Manager
Cherry	Felix

Note:

- 1. This report will be invalid if reproduced in whole or in part.
- 2. This report refers only to the specimen(s) submitted to test, and is invalid if used separately.
- 3. This report is only valid with the examination seal and signature of this institute.
- 4. The tested specimen(s) will only be preserved for thirty days from the date issued, if not collected by the applicant.
- 5. This report is only responsible for the samples tested.



CNAS ilac-



Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Email: engineer@iclab-cn.com

Report No:	SZ09062021001
Date:	2021/09/06
Page:	2/22

Items test

$ \sqrt{} $	External	visual	ins	pection

Tel: 0755-83765367

- ☐ Pin Correlation Test
- ☐ Programming test
- ☐ Solder ability Analysis
- ☑ Radiography (X-ray)
- ☑ ROHS test
- ☐ Key Functional Testing (KFT)
- □ Baking
- ☐ Tape and Reel
- ☑ Internal visual inspection
- ☐ Top permanency test
- ☑ Heated Chemical Test

Methods & Equipment

1.1 Applicable Standard

AS6081

1.2 Optical Microscope

Equipment Spec:

Top view: FINIAL Hi-scope System SEZ-260: X7 ~ X45 FJ-3A: X50-X500

1.3 Digital Caliper

• Equipment Spec:

MASTERPROOF: Standard Digital Caliper 0-150mm

1.4Radiography (X-ray)

• Equipment Spec:

Hardware:XiDAT Dage XD6500

Software:11.56-DD6058

Magnification in excess of 2800x

Resolution below 2um Energy:80KV/40uA



Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Email: engineer@iclab-cn.com

CNAS	ilac-mra
Report No:	SZ09062021001
Date:	2021/09/06
Page:	3/22

1.5 ROHS test

• Equipment Spec: ICP-OES

1.6 Testing Environment

Ambient Temperature: 25±5°C
Relative Humidity: 45%-65% RH

Tel: 0755-83765367

1.7 Testing Base

• [ADI ADXL357BEZ-RL7]

https://www.analog.com/media/en/technical-documentation/data-sheets/ADXL356-357.pdf

Analysis Summary

External Visual Inspection:

Applicable Standard: AS6081

External Visual Inspection on 122 PCS(B1 to B41,C-1 to C-41,D1 to D40) samples. No secondary coating, sanding marks, crack or chips were observed on all inspected. Leads were in acceptable condition. Devices package and dimension matched to manufacturer's specification. All devices passed the external visual inspection.

Specification dimension:

L: 5.85-6.25 MM W: 5.85-6.25 MM H: 2.20 REF MM

Measurement dimension:

L: 6.00 MM W: 6.02 MM H: 2.27 MM



Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Tel: 0755-83765367 Email: engineer@iclab-cn.com

CNAS	ilac-mra
Report No:	SZ09062021001
Date:	2021/09/06
Page:	4/22

X-ray Analysis:

Applicable Standard: AS6081

X-ray Inspection 49 PCS(B1 to B16,C-1 to C-16,D1toD17)samples . No structure or bonding wire abnormal was found.

ROHS Testing:

Applicable Standard: AS6081

ROHS testing on 3 PCS samples. Cd (PPM), Hg(ppm) and Pb (ppm) tests comply with ROHS standards.

Heated Chemical Test:

Applicable Standard: AS6081

Heated Chemical Test were verified 3PCS (B1, C-1, D1) samples, all samples passed Heated Chemical Test.

Internal Visual Inspection:

Applicable Standard: AS6081

Internal Visual Inspection was verified on 3PCS (B1, C-1, D1) samples. 2 dies (Die1&Die2) were found.

Die1: Manufacturer ADI marking were found with 2016 copyright year. Die marking XM357A were found on the die surface.

Die2: Manufacturer ADI marking were found with 2015 copyright year. Die marking XL355 were found on the die surface.

Summary: All samples show the same structures and marking and samples confirmed to be a ADI device.







Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com

	"15abate"
Report No:	SZ09062021001
Date:	2021/09/06
Page:	5/22

External Visual Inspection Result:		
External Visual Criteria	Yes/No	Result
Mix-up	No	Pass
Top Scratches	No	Pass
Bottom Scratches	No	Pass
Residues	No	Pass
Indentation	No	Pass
Contamination	No	Pass
Cracks	No	Pass
Copper defect	No	Pass
Oxidization	No	Pass
Coplanarity	Yes	Pass
Sanding Marks	No	Pass
Secondary Coating	No	Pass
Top permanency Test	N/A	N/A



...





Add: F/r 401Building A, Ying Da Feng industrial No,393, Jihua Rd.Long
Gang Dis. Shenzhen China

Email: engineer@iclab-cn.com


Report No:	SZ09062021001
Date:	2021/09/06
Page:	6/22

1. Device Description:

Tel: 0755-83765367

The analog output ADXL356 and the digital output ADXL357 are low noise density, low 0 g offset drift, low power, 3-axis accelerometers with selectable measurement ranges. The ADXL356B supports the ± 10 g and ± 20 g ranges, the ADXL356C supports the ± 10 g and ± 40 g ranges, and the ADXL357 supports the ± 10 g, ± 20 g, and ± 40 g ranges.

2. Package Dimensions:



7-2016-



Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Email: engineer@iclab-cn.com

CNAS	ilac-mra
Report No:	SZ09062021001
Date:	2021/09/06
Page.	7/22

3. Receiving Inspection:

Tel: 0755-83765367

Gross Weight	1036 g	Parts Total	2500 PCS
Number Of Boxes	4	Full Label	Exist
Package type	Reel	Moisture protection	Non Present
MSL	N/A	ESD protection	Non Present

Note: All devices contain 2500 PCS samples.

Test samples contain 41 PCS of D/C 2108(B1 to B41), 41 PCS of D/C 2106(C-1 to C-41) and 40 PCS of D/C 2113(D1 to D40).





CNAS





Add: F/r 401Building A, Ying Da Feng industrial No,393, Jihua Rd.Long
Gang Dis. Shenzhen China

Tel: 0755-83765367 Email: engineer@iclab-cn.com

Report No: SZ09062021001

Date: 2021/09/06

Page: 8/22

Label-3



Label-4



Label-5



Received View-3



CXO.lab

Chuangxin Online Test Center Laboratory

Add: F/r 401Building A, Ying Da Feng industrial No,393, Jihua Rd. Long Gang Dis. Shenzhen China Tel: 0755-83765367

Email: engineer@iclab-cn.com

CNAS	ilac-mra	IEC.
Report No:	SZ0906	2021001
Date:	2021/09	9/06
Page.	9/22	

4. External Visual Inspection:

Applicable Standard: AS6081


External Visual Inspection on 122 PCS(B1 to B41,C-1 to C-41,D1 to D40) samples. No secondary coating, sanding marks, crack or chips were observed on all inspected. Leads were in acceptable condition. Devices package and dimension matched to manufacturer's specification. All devices passed the external visual inspection.

Specification dimension:

L: 5.85-6.25 MM W: 5.85-6.25 MM H: 2.20 REF MM

Measurement dimension:

L: 6.00 MM W: 6.02 MM H: 2.27 MM





Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com

CNAS	ilac-MRA	IEC.
Report No:	SZ0906	2021001
Date:	2021/09	9/06
Page:	10/22	•

B1-Side




B1-Laser Marking




B1-Pin 1



B1-Bottom Leads



B1-Leads End



B1-L = 6.00 MM









Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com

	San Park
Report No:	SZ09062021001
Date:	2021/09/06
Page:	11/22

	B 1	-W	=6.	.02	MN	
--	------------	----	-----	-----	----	--




B1-A = 2.27 MM



C-1-Top









D1-Top

D1-Bottom







Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China Tel: 0755-83765367


Email: engineer@iclab-cn.com

CNAS	ilac-mra	IEC.
Report No:	SZ0906	2021001
Date:	2021/09	9/06
Dage.	12/22	

5.X-ray Analysis:

Applicable Standard: AS6081

X-ray Inspection 49 PCS(B1 to B16,C-1 to C-16,D1toD17)samples. No structure or bonding wire abnormal was found.










Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com


	100,000
Report No:	SZ09062021001
Date:	2021/09/06
Page:	13/22

C-1-Top View-All




C-1-Side View-All







C-1-Side View-Zoom




D1-Top View-All



D1-Top View-Zoom















Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com

	Tallian Co.
Report No:	SZ09062021001
Date:	2021/09/06
Page:	14/22

D1-Side View-All

D1-Side View-Zoom





CXO.lab

Cd(ppm)

0

ND

Chuangxin Online Test Center Laboratory

Add: F/r 401Building A, Ying Da Feng industrial No,393, Jihua Rd. Long Gang Dis. Shenzhen China Tel: 0755-83765367

Email: engineer@iclab-cn.com

CNAS	ilac-mra	
Report No:	SZ09062021001	
Date:	2021/09/06	
Page.	15/22	

6. ROHS Testing:

Applicable Standard: AS6081

ROHS testing on 3 PCS samples. Cd (PPM), Hg(ppm) and Pb (ppm) tests comply with ROHS standards.

B1						
Element	Intensity	Content (ppm)	Equipment	Error (ppm)	Limits (ppm)	Result
Cd(ppm)	0	ND	ICP-OES	0.00	100	Pass
Hg(ppm)	0	ND	ICP-OES	0.00	1000	Pass
Pb(ppm)	0	ND	ICP-OES	0.00	1000	Pass
C-1						
Element	Intensity	Content (ppm)	Equipment	Error (ppm)	Limits (ppm)	Result
Cd(ppm)	0	ND	ICP-OES	0.00	100	Pass
Hg(ppm)	0	ND	ICP-OES	0.00	1000	Pass
Pb(ppm)	0.00015	768.47	ICP-OES	153.69	1000	Pass
D1						
Element	Intensity	Content (ppm)	Equipment	Error (ppm)	Limits (ppm)	Result
21()) ID	ICD OFG	0.00	100	

ICP-OES

0.00

100

Pass





Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China Tel: 0755-83765367

Email: engineer@iclab-cn.com


	7-3 LIL 100
Report No:	SZ09062021001
Date:	2021/09/06
Page:	16/22

Hg(ppm)	0	ND	ICP-OES	0.00	1000	Pass
Pb(ppm)	0	ND	ICP-OES	0.00	1000	Pass

7. Heated Chemical Test:

Applicable Standard: AS6081

Heated Chemical Test were verified 3PCS (B1, C-1, D1) samples, all samples passed Heated Chemical Test.










Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China
Tel: 0755-83765367 Email: engineer@iclab-cn.com

	A STATE OF THE STA
Report No:	SZ09062021001
Date:	2021/09/06
Page:	17/22




D1_Before Top View



D1_After Top View







Add: F/r 401Building A, Ying Da Feng industrial No,393, Jihua Rd. Long Gang Dis. Shenzhen China Tel: 0755-83765367

Email: engineer@iclab-cn.com

CNAS	ilac-MRA	IEC.
Report No:	SZ0906	2021001
Date:	2021/09	9/06
Page.	18/22	

8.Internal Visual Inspection:


Applicable Standard: AS6081

Internal Visual Inspection was verified on 3PCS (B1, C-1, D1) samples. 2 dies (Die1&Die2) were found.

Die1: Manufacturer ADI marking were found with 2016 copyright year. Die marking XM357A were found on the die surface.

Die2: Manufacturer ADI marking were found with 2015 copyright year. Die marking XL355 were found on the die surface.

Summary: All samples show the same structures and marking and samples confirmed to be a ADI device.






Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Email: engineer@iclab-cn.com




B1_Die2-Topography

Tel: 0755-83765367




B1_Die2-Corner-1




B1_Die2-Logo


B1_Die2-Corner-2



C-1_Die1-Topography



C-1_Die1-Logo







CNAS






Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China

Tel: 0755-83765367


Email: engineer@iclab-cn.com

	75.4.11.477
Report No:	SZ09062021001
Date:	2021/09/06
Page:	20/22


C-1_Die1-Corner-1




C-1_Die1-Corner-2




C-1_Die2-Topography




C-1_Die2-Logo



C-1_Die2-Corner-1



C-1_Die2-Corner-2






Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China Tel: 0755-83765367


Email: engineer@iclab-cn.com

CNAS	ilac-MRA	IEC.
Report No:	SZ09062021001	
Date:	2021/09	9/06
Page:	21/22	

D1_Die1-Topography




D1_Die1-Corner-1




D1_Die1-Logo


D1_Die1-Corner-2




D1_Die2-Topography



D1_Die2-Logo














Add: F/r 401Building A, Ying Da Feng industrial No,393,Jihua Rd.LongGang Dis. Shenzhen China Tel: 0755-83765367


Email: engineer@iclab-cn.com

	75.4,15,407
Report No:	SZ09062021001
Date:	2021/09/06
Page:	22/22









End

For more information, please visit: http://www.iclabcn.com

CXO Lab WeChat official account

